

# State of Utah

# Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

# Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:						
Company	Mike W. Glasson Environmental Coordinator					
OGM	Karl Houskeeper Environmental Scientist III					

# **Inspection Report**

Permit Number:	C0070019		
Inspection Type:	PARTIAL		
Inspection Date:	Friday, July 06, 2007		
Start Date/Time:	7/6/2007 9:00:00 AM		
End Date/Time:	7/6/2007 4:00:00 PM		
Last Inspection:	Tuesday, June 05, 2007		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 88 Deg. F. InspectionID Report Number: 1345

Types of Operations

Accepted by: dhaddock 7/23/2007

Permitee: ANDALEX RESOURCES INC TOWER DIVISION Operator: ANDALEX RESOURCES INC TOWER DIVISION

Site: CENTENNIAL MINE

Address: 6750 AIRPORT RD, PO BOX 902 PRICE UT 84501

County: CARBON

Permit Type: **PERMANENT COAL PROGRAM** 

Permit Status: ACTIVE

#### **Current Acreages**

6,602.02	Total Permitted		
35.27	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

#### Mineral Ownership

Underground ✓ Federal State Surface County Loadout Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site.

Citation #10007 was issued, see item #4a.

Inspector's Signature:

Karl Houskeeper, Environmental Scientist III

**Date** 

Friday, July 06, 2007

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070019 Inspection Type: PARTIAL

Inspection Date: Friday, July 06, 2007

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		<b>✓</b>	
2.	Signs and Markers	<b>~</b>		<b>V</b>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	<b>✓</b>		<b>✓</b>	<b>V</b>
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	<b>✓</b>		<b>V</b>	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches	<b>~</b>	<b>V</b>		
7.	Coal Mine Waste, Refuse Piles, Impoundments	<b>~</b>	<b>V</b>		
8.	Noncoal Waste	<b>✓</b>		<b>V</b>	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.1	Roads: Drainage Controls				
17.	Other Transportation Facilities	<b>~</b>		<b>~</b>	
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070019 Inspection Type: PARTIAL

Inspection Date: Friday, July 06, 2007

Page 3 of 3

#### 1. Permits, Change, Transfer, Renewal, Sale

A revised surface facilities map has been prepared and will be submitted to the Division. The map should show the existing structures and relocation of facilities associated with the new ventilation fan construction.

#### 2. Signs and Markers

The mine permit ID signs are located at the contact points of public access to the permit area. The signs contained the required information.

#### 4.a Hydrologic Balance: Diversions

Citation #10007 issued for failure to maintain disturbed diversion DD-7. A pickup truck was parked in the diversion, preventing it form functioning according to the approved design contained within mining and reclamation pan (MRP). The permittee has been warned on several prior inspections that this practice would result in enforcement action. The last inspection June 5, 2007 stated "... Andalex Resources was informed that in the future if a vehicle is found parked in a diversion that a citation will be issued." The citation was terminated later in the day when the truck was removed from the diversion. Future infractions will result in additional citations.

### 4.d Hydrologic Balance: Water Monitoring

First quarter 2007 water monitoring information is in the EDI website and has been uploaded. Water monitoring is current.

#### 8. Noncoal Waste

Several items of noncoal waste were spread throughout the facility. This has been a problem in the past. Citation 10003 was issued in the past for failure to control and contain noncoal waste. Measures need to be taken to control noncoal waste to avoid future compliance problems.

#### 17. Other Transportation Facilities

The Aberdeen loadout pad access to the county road shows evidence of material transfer from the pad to the county road. As a result the area is exhibiting dust problems. This problem was observed on the June 5, 2007 inspection and again during this inspection. Measures need to be taken to prevent and/or control this problem. The resultant dust can become an air quality issue, which will be addressed by compliance action. Drainage from the area is contained or controlled by the existing disturbed sedimentation pond.